

ERROR CODES

OBD-II SCAN

Emissions		 1 codes found
P0300	Random/Multiple Cylinder Misfire Detected	
Recommended fixes		SPARK PLUG
Maintainence		 No codes found
Safety		 No codes found
Comfort		 No codes found
Other		 5 codes found
P127C	No description available	
P151E	Active Grille Air Shutter 1 Actuator Signal Message Counter Incorrect	
P26C8	Chassis Control Module 1 Requested MIL Illumination	
P0192	Fuel Rail Pressure Sensor Circuit Low Bank 1	
P16A1	No description available	
Recommended fixes		

PHOTOS



Windshield, Broken,
Replacement Required

Spare Wheel, Missing,
Replacement Required



Right Rear Wheel, Curb
Rash, 1 to 2 inches

Right Qtr Panel, Dent(s)
W/ Paint Dmg, 2 to 3
inches

Right Front Wheel, Curb
Rash, 3 to 4 inches

Left Front Seat, Worn,
Replacement Required



Left Rear Tire, Worn,
Replacement Required

Front Bumper, Chipped,
10 or more

Tire Inflator, Missing,
Replacement Required

HISTORY

Clean Title

This vehicle has never been deemed a total loss.

2 Owners

This vehicle has 2 owner(s)

Odometer

Last reading reported at 95,580 miles.

No Accidents

This vehicle has not been reported in any accidents

No Open Recall

This vehicle does not have any open recalls.

Service History

87 Service History record associated with this vehicle.

Engine Engages

Copart verified that the engine engages.

Transmission Engages

Copart verified that the transmission engages.

ACCIDENT AND ODOMETER HISTORY

Accident and Damage

✓ No accidents reported

Odometer (95,580 mi Actual)

✓ No issues found

✓ State Title Odometer Check	No issues found
✓ Auction Odometer Check	No issues found
✓ Odometer Calculation Check	No issues found

OBDII Recommended Repairs

🔧 1 Recommended Repairs

SPARK PLUG