

ERROR CODES

OBD-II SCAN

|                                                                                                                |                                                                                                                                                      |
|----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------|
| Emissions  2 codes found    |                                                                                                                                                      |
| P0106                                                                                                          | Manifold Absolute Pressure/Barometric Pressure Sensor Circuit Range/Performance                                                                      |
| P2227                                                                                                          | Barometric Pressure Sensor 'A' Circuit Range/Performance                                                                                             |
| Recommended fixes                                                                                              | MANIFOLD ABSOLUTE PRESSURE SENSOR<br>BAROMETRIC PRESSURE SENSOR WIRING HARNESS<br>BAROMETRIC PRESSURE SENSOR CONNECTOR<br>BAROMETRIC PRESSURE SENSOR |
| Maintenance  No codes found |                                                                                                                                                      |
| Safety  No codes found      |                                                                                                                                                      |
| Comfort  No codes found     |                                                                                                                                                      |
| Other  2 codes found      |                                                                                                                                                      |
| P00C7                                                                                                          | Intake Air Pressure Measurement System - Multiple Sensor Correlation Bank 1                                                                          |
| P257D                                                                                                          | Engine Hood Switch Circuit Range/Performance                                                                                                         |
| Recommended fixes                                                                                              |                                                                                                                                                      |

## PHOTOS



Roof, Hole(s), 2 to 3 inches

Left Rear Wheel, Rust,  
Repair Required



Right Rear Wheel, Curb  
Rash, > 12 inches



Right Front Wheel, Curb  
Rash, > 12 inches



Center Console, Missing,  
Replacement Required



Rear Bumper, Dent(s) W/  
Paint Dmg, > 12 inches



Warning Light - Engine, On,  
Unacceptable



Left Drip Rail, Hole(s), 1/2 to  
1 inch



Right Drip Rail, Hole(s), 1/2  
to 1 inch



Overall Vehicle, De-identify,  
Removal Required

## HISTORY

### Clean Title

This vehicle has never been deemed a total loss.

### 1 Owners

This vehicle has 1 owner(s)

### Odometer

Last reading reported at 129,289 miles.

### No Accidents

This vehicle has not been reported in any accidents

### No Open Recall

This vehicle does not have any open recalls.

### Service History

1 Service History record associated with this vehicle.

### Engine Engages

Copart verified that the engine engages.

### Transmission Engages

Copart verified that the transmission engages.

## ACCIDENT AND ODOMETER HISTORY

### Accident and Damage

✓ No accidents reported

### Odometer (129,289 mi Actual)

✓ No issues found

✓ State Title Odometer Check

No issues found

✓ Auction Odometer Check

No issues found

✓ Odometer Calculation Check

No issues found

### OBDII Recommended Repairs

🔧 4 Recommended Repairs

MANIFOLD ABSOLUTE PRESSURE SENSOR

BAROMETRIC PRESSURE SENSOR WIRING HARNESS

BAROMETRIC PRESSURE SENSOR CONNECTOR

BAROMETRIC PRESSURE SENSOR